HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HYATTSVILLE HARDWARE 5121 Baltimore Avenue Hyattsville Prince George's County Maryland HABS NO. MD-1042

- Jack E. Boucher, photographer, April 4, 1991 & April 13, 1992
- MD-1042-1 GENERAL VIEW OF WEST (FRONT) ELEVATION
- MD-1042-2 WEST (FRONT) ELEVATION
- MD-1042-3 WEST (FRONT) DOORWAY
- MD-1042-4 NORTH SIDE ELEVATION OF REAR SECTION
- MD-1042-5 INTERIOR VIEW OF FRONT SECTION OF NORTH WALL LOOKING NORTHWEST, SHOWING COUNTERS AND BUILT-IN SHELVING
- MD-1042-6 INTERIOR VIEW OF REAR SECTION OF NORTH WALL LOOKING NORTHWEST, SHOWING BUILT-IN SHELVING AND BINS FOR NAILS
- MD-1042-7 INTERIOR VIEW OF WEST (REAR) DOORWAY FROM STORE INTO STORAGE ROOM
- MD-1042-8 INTERIOR VIEW, SECOND FLOOR, REMNANTS OF ORIGINAL ELECTRICAL SYSTEM AT TOP OF STAIRWAY, SOUTH WALL, LOOKING SOUTHWEST
- MD-1042-9 INTERIOR VIEW, SECOND FLOOR, VIEW OF CARGO LIFT, REAR SECTION, LOOKING NORTHWEST
- MD-1042-10 INTERIOR VIEW, SECOND FLOOR WORK BENCH AND TOOLS, CENTER SECTION, LOOKING NORTHWEST
- MD-1042-11 INTERIOR VIEW, SECOND FLOOR, VIEW LOOKING EAST INCLUDING STAIRWAY TO THIRD FLOOR (NOTE SECTION OF WOODEN PIPE LEANING AGAINST SHELF POST TO RIGHT)
- MD-1042-12 INTERIOR VIEW, THIRD FLOOR, VIEW LOOKING NORTHEAST AT ENTRYWAY FROM STAIRHALL
- MD-1042-13 INTERIOR VIEW, THIRD FLOOR, VIEW LOOKING NORTHWEST